


26.1300.20 SW90 Swivel 90°, sst, 1/4 MF Bsp

26.1300.40 SW90 Swivel 90°, sst, 3/8 MF Bsp



26.1300.42 SW90 Swivel 90°, sst, 1/4F-3/8M Bsp

26.1350.20 SW90-E Swivel 90°, sst sc.1/4Bsp MF Epdm

		K1	K2	K3	K4	
1	10.1003.00R Snap ring, E 18 Sst.	1				5
2	14.4048.00R Washer, 18,3x24x0,5 mm Sst.	1	•	•		10
3	26.1301.31R Housing -SW90, 1/4F Bsp (1,2,3)	1				5
3	26.1303.31R Housing -SW90, 3/8F Bsp (4)	1				3
4	26.1302.51R Pierced screw, 1/4M Bsp Sst. (1)	1				3
4	26.1304.51R Pierced screw, 3/8M Bsp Sst. (4)	1				3
4	26.1304.51R Pierced screw, 3/8M Bsp Sst. (2)	1				3
5	10.4083.00R Back-up ring, opn. 14,7x18x,4 mm	2	•	•		10
6	10.3091.10R O-ring, 2x14 mm Vi 70	2	•			10
6	10.3091.18R O-Ring 2 x 14 mm Epdm (3)	2		•		10

K1	26.1305.24 Spares kit -Sw90, 3x1pcs.					1
K2	26.1353.24 Spares kit -Sw90E- 1/4-. 3x1pcs.					1

(1) 26.1300.20 (2) 26.1300.42 (3) 26.1350.20 (4) 26.1300.40